Crawford County R FEE BOOK 2006-0961 4/07/2006 @ 12:11PM PLC PLAT CORNER CERBook: Total Fees: \$7.00

INDEXED FOLLOW UP SCANNED

WILKE LAND SURVEYING

401 1800th Street

Panama, Iowa 51562

(712)489 - 2898


UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE


SECTION 5 TOWNSHIP 85N RANGE 41W COUNTY CRAWFORD


Certificate Prepared For: Survey of Part of the NE1/4 of Section 5


Monument Description and Remarks:

- 1 Found ½" dia. pipe w/crimped top 1.2' deep in road and in line with fence South. Probed 5' under and no conc. was found. The ties from the Crawford County Engineer's Office were the same as from the Ida County Engineer's Office and they wouldn't fit the found pipe or each other when crossing them in the field.
- ② Found conc. mon. without disc 1.1' deep in road. No metal detection and no ties were left so did a lot of digging until found. Set P.K. nail in top center of conc. mon. Set ¾" rebars on North and South sides just below the top of the C.M. for detection purposes only.
- 3 Set %" x 24" rebar w/orange cap PLS #17048 Flush at the intersection point of lines from opposite 1/4 Corners of Section 5.
- (4) Set (Witness Pin) %" x 24" rebar w/orange cap PLS #17048 Flush 75.00' Westerly of the Calculated E1/4 Corner on the South line of the NE1/4. The E1/4 Corner was calculated by single proportion between the SE Corner and NE Corner of Section 5. It lined up good with the fallen fences extending West and North of the deep creek. The fence extending South of the creek was +/- 7.8' West of the Section line.











ean

My license renewal date is December 31, 2007

Pages or sheets covered by this seal: This page only



5.012			
SET 5/8" D	A. BY 24" PLS #170-		CAP



List Corners to be Indexed					
<u>Corner</u>	Section	Twp.	Range		
N1/4 CORNER	5	85N	41W		
NE CORNER	5	85N	41W		
CENTER	5	85N	41W		
(WITNESS PIN TO) E1/4 CORNER	5	85N	41W		